



Plane Stress

z-face has no stress

Normal Stresses

$\sigma_x$  and  $\sigma_y$

Shearing Stresses

$$\tau_{xy} = \tau_{yx}$$

3 independent stress components

